INSPECTION RECOMMENDATION

Maint.Zone: D&R	Plant: #4CU	RECOM #: 955-007-001
Priority: 2-Planned Shutd		Passport#:
		EWO #:
PIt EqNo: PIPING	EQID No:	
Service: #4 SIDECUT PIPING	;	Page#:
No - Will this work lead to op No - Is this repair or replacen No - Does this involve develo No - Does the work involve th No - Will this impact upstrear	als or catalysts be used? (See RI-313 for new chemicals, Oprs. Cooreration outside established limits? Which equipment?	for new equipment) ng. 001 is due for external cessibility is only possible ed drawing. ed drawing. e completed.
Cost Estimate by:		Total Total rl Cost: Cost:
Inspector: K.L. Garber, x2-1706 Date Reco Written: May 4, 2001		
Engineer:	Date: Operations:	Date :

ERG (FER - OSI Inspection Form - Rev.: 6/1/2000)

Date Printed:

5/4/2001

